



West view of Eveleth Avenue culvert repair.



North view culvert repair job on the south end of Eveleth Avenue.





East view of the west side of Isle Avenue culvert replacement.



East view of the west side of Isle Avenue culvert replacement.





Removed Isle Avenue culvert.





Removed Guam Avenue culvert.



Removed Guam Avenue culvert.





New culvert for Guam Avenue.



Guam Avenue culvert replacement.





North view, east side of Guam Avenue.



North view of the west side of Guam Avenue.





North view of the east side of Eveleth Avenue.



West view of the north side of 307th Street.





Dutch Creek sign on 300th St. Produced and placed by Dakota County.



Hazelwood Creek sign on 295th St. Produced and placed by Dakota County.





Northeast view of Eveleth Avenue, south of 307th Street. April 18, 2019



North view of Eveleth Avenue. April 18, 2019





Northwest view of Eveleth Avenue. April 18, 2019



Repairing cut and damaged culvert on Eveleth Avenue