



Washed out exit area of North Holyoke Avenue culvert before repairs.



Lower exit area of North Holyoke Avenue culvert before repairs.





North Holyoke Avenue culvert after repairs.



North Holyoke Avenue culvert exit area after repairs.





Grading Jamaica Avenue after new aggregate delivery.



Watering Jamaica Avenue during grading work.





Finish grading the edge of Jamaica Avenue.



Dust control product application on 285th. Street.





Field driveway culvert area before repairs on 300th. Street.



300th Street culverts during repair work.





Ditch re-shaping and repair on 300th. Street.



Ditch re-shaping in driveway areas on 300th. Street.





Ditch area at Isle Avenue and 295th Street before improvement.



West side of North Isle Avenue after ditch repair & Shaping.



West side of Isle Avenue after ditch re-shaping and repair .