

1



West view, of the east side of Iran Path bridge before rock placement

2



Northeast view of west side of Iran Path bridge



3



Northeast view of west side of Iran Path bridge

4



Northwest view, east side of Iran Path bridge



5



East view of southside, west end of 315th Street

6



West view of the southside of the west end of 315th Street



7



West view, south side of the west end of 315th Street

8



West view of the west end of 315th Street



9



South side, west end of 315th Street

10



West view of the RR track area of 315th Street



11



Watering and grading new aggregate on 315th Street

12



New aggregate surface on the west end of 315th Street



13



Grading the west end of 315th Street

14



West view of improved 315th Street, late summer



15



Vegetation established. West view 315th Street, late summer

16



West view, 315th Street



17



Culvert replacement. East side of north end of Dunbar Avenue

18



East view, north side of 285th Street ditch reshaping



19



West view, north side of the east end of 285th Street

20



Southwest view of the east end of 285th Street



21



West view of the northside of 285th Street West

22



West view, of the east end of 285th Street West

The 285th Street project was funded by Dakota County